




# VOLUME AND BATTERY ON A S PLUS COMPUTER BOARD

THIS IS THE  
VOLUME CONTROL



THIS IS THE  
BATTERY



you should use a DC volt meter  
to measure the battery voltage  
to make sure it is still at 3 Volts or more.  
Normally a fresh battery is rated  
at 3.6 Volts and is a Lithium Ion type.

*HARBOR FREIGHT SELLS  
A CHEAP VOLTMETER IF  
YOU DON'T HAVE ONE*